COMPLETION REPORT

1. Name of Work : **PROVIDING AND SUPPLYING WATER THROUGH WATER TANKERS IN BAGALAGUNTE WARD NO.14, T.DASARAHALLI SUB DIVISION.**

2. Sanctioned Estimate No. & Dt : TWD : 048/13-14 dt 31.7.2014

3. Head of Account which is Chargeable : pdy 1802

4. Work Order No. & Dt : EE/DD/11/14-15 dt 5-5-2014

5. Name of Contractor : **TECHNICAL MANGER (WEST) KRIDL**

6a. Time stipulated for completion of work :

b. Delay in execution of work : --

7. Measurement recorded in : M.B. No. 826 Page No. 8255

8. Check measurement of the Asst. : M.B. No. 826 Page No. 8255

Asst. Exe. Eng. / Exe. Eng :

9. Name of the Office / Official incharge of the work : AEE (DSD)

10. a) Asst. Engineer : D-S ಮಂಜುನಾಥ

b) Asst. Exe. Engineer : ಕಂಠಿಸಿದ.

Sanctioned estimated amount	Amount claims as per actually vide as per bills	DIFFERENCE	
		Excess	Savings
20.00	19858192	—	141808

ಮುಖ್ಯ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು.

1) Certified that the above work has been completed within the stipulated time noted in the work order.
2) Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3) Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

ASST. ENGINEER

ASST. EXECUTIVE ENGINEER
SUB DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE

EXECUTIVE ENGINEER
ಮುಖ್ಯ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು.
Bruhat Bangalore Mahanagara Palike,
Dasarahalli Zone, Bangalore-57.

ACCOUNTS SURTD. ( )